

C171



CLICK TO ORDER PARTS

shop.monsterjanitorial.com

TABLE OF CONTENTS

C171 Cover Shot	3
Main Assembly	5

C171 Cover Shot




Rendered by LeadVenture, Inc.

C171 Cover Shot

Ref Number	Part Number	Part Description	Context Notes	Quantity
------------	-------------	------------------	---------------	----------

Main Assembly



Rendered by LeadVenture, Inc.

Main Assembly

Ref Number	Part Number	Part Description	Context Notes	Quantity
1	X8911-K	Complete Handle Assembly		1
	M8600-3	Replacement Metal Handle Assembly		
2	X8941	Handle Grip		2
3	X8914	Thumb Switch Actuator		1
4	X8927	Label		1
5	X8923	Insulation Sheet		1
6	X1039	Momentary Switch w/Nuts 25A		1
7	X8013	Cord Hook		1
8	X8023	Circuit Breaker 15A w/Nuts		1
9	X8266	Screw #10-32 x 1"		3
10	X8982	Label		1
11	X8965	Metal Motor Cover		1
12	X8106	Spacer		3
13	X8265	Screw 1/4-20 x 3/4"		2
14	X8020	Countersunk Washer		2
15	X8024	Wheel 5" x 1-1/4"		2
16	X8101	Spring Washer		4
17	X8981	Motor 120/240 VAC 60 Hz 1HP		1
18	X8400A	Label		1
19	X8966	Motor Base		1
20	X8967A	17" Metal Brush Housing w/Bumper		1
	X8969	17" Bumper ONLY		1
21	X8212	Lock Washer		4
22	X8218	Washer		4
23	X8219	Washer		4
24	72455A	Screw 1/4-20 x 1-3/4"		4

Ref Number	Part Number	Part Description	Context Notes	Quantity
25	X8977	Pivot Pin		1
26	X9575	Axle 1/2"		1
27	X8107	Spacer		2
28	X8807L	Handle Brace w/Slot		1
29	X8807R	Handle Brace w/Hole		1
30	X8989	Cord 50' x 14/3 SJTOOW 50"		1
31	X8016	Plastic Handle Clamp Knob		1
32	X1456	Handle Lock Clamp		1
33	X1184	Cam Lever Assembly		1
34	X8953	Start Capacitor 450uF		1
35	X8038	Run Capacitor 240VAC/60uF		1
Not Shown	MS1369AS	Power Cord Assembly 14/3 x 50' STW		1