

PD500



CLICK TO ORDER PARTS

shop.monsterjanitorial.com

TABLE OF CONTENTS

PD500 Cover Shot	3
Main Assembly	5

PD500 Cover Shot




Rendered by LeadVenture, Inc.

PD500 Cover Shot

Ref Number	Part Number	Part Description	Context Notes	Quantity
------------	-------------	------------------	---------------	----------

Main Assembly



Main Assembly

Ref Number	Part Number	Part Description	Context Notes	Quantity
1	X8876REPRO	Housing		1
2	PD5D	Plastic Dryer Squirrel Cage w/Metal Insert	Squirrel Cage PD5=Metal Squirrel Cage w/lock nut PD5D=Plastic Squirrel Cage w/metal lock nut	1
4	X8261	Screw #6 x 1/2" (Black)		11
7A	X8881-120	Motor 1/2HP 120VAC w/Capacitor		1
8	X8875	Motor Control Panel		1
9	X8903	Screw M4 x 6		2
10	PD1K	Knob		1
12	X8008	Plastic Cord Protector		1
13	PD8	Strain Relief		1
14	X8926	Yellow Power Cord 20' x 16/3 SJTW		1
15	X8897	Switch		1
16	X8964	Screw 3/8-16 x 1/2"		3
17	X8871	Discharge Grill		1
18	X8526	Keps Nut		2
19	PX73	Screw #8-32 x 1"		2
20	X8929	Left Foot		1
22	X8874	Dryer Kickstand		1
23	X8928	Right Foot		1
24	PD3B	Tall Dryer Foot		2
25	X8946	Rivet		4