

PDH1



CLICK TO ORDER PARTS

shop.monsterjanitorial.com

TABLE OF CONTENTS

PDH1 Cover Shot	3
Main Assembly	5

PDH1 Cover Shot




Rendered by LeadVenture, Inc.

PDH1 Cover Shot

Ref Number	Part Number	Part Description	Context Notes	Quantity
------------	-------------	------------------	---------------	----------

Main Assembly



Rendered by LeadVenture, Inc.

Main Assembly

Ref Number	Part Number	Part Description	Context Notes	Quantity
1	X9728	Switch Label		1
2	X9831	Knob		1
3	X9731	Cap		4
4	X9727	Warning Label		1
5	X8903	Screw M4 x 6		2
6	X8278	Screw #8-32 x 1/2"		2
7	X9701	Top Housing		1
8	X9726	Front Label		1
9	X8260	Nyloc Nut		2
10	X1002	Power Cord 14/3 x 20' SJTW		1
11	X8897	Switch		1
12	X1023	Fan Blade		1
Not Shown	X9054	Set Screw 5/16-24 x 3/8"	Set Screw should be ordered with Fan Blade	1
13	X9702	Bolt 1/4-20 x 2-3/4"		5
14	X8235	Washer		5
15	X9705	Rubber Grommet		1
16	04-0286-0000	Cable Clamp		1
17	X8459	Serial Number Label		1
18	X8976	Warning Label		1
19	X9676	Screw #8-18 x 3/4"		3
20	X9676	Screw #8-18 x 3/4"		10
21	X8237	Nyloc Nut		5
22	X8871	Discharge Grill		1
23	X9674-115.2-AL	Motor 115 VAC w/14uf Capacitor		1

Ref Number	Part Number	Part Description	Context Notes	Quantity
Not Shown	X9674C	Capacitor 14uF		1
24	X9700	Bottom Housing		1
25	X8946	Rivet		2
26	PD3B	Tall Dryer Foot		2
27	X9704	Screw #8-18 x 3/1/2"		2
28	X8256	Keps Nut		2
29	PX73	Screw #8-32 x 1"		2
30	X8874	Dryer Kickstand		1
31	X8929	Left Foot		1
32	X8261	Screw #6 x 1/2" (Black)		4
33	X8928	Right Foot		1
34	X1022	Circuit Breaker 9A		1
35	X9757	Power Outlet Assembly		1
37	X1004	Qualified Made In The USA Label		1