

98778




CLICK TO ORDER PARTS

TABLE OF CONTENTS

Main Assembly	3
Wiring Diagram	6

Main Assembly



SCALE 0.250


Rendered by LeadVenture, Inc.

Main Assembly

Ref Number	Part Number	Part Description	Context Notes	Quantity
1	04-0286-0000	Cable Clamp		1
2	PD3B	Tall Dryer Foot		2
3	X8235	Washer		5
4	X8237	Nyloc Nut		5
5	X8256	Keps Nut		2
6	X8278	Screw #8-32 x 1/2"		2
7	X8459	Serial Number Label		1
8	X8871	Discharge Grill		1
9	X8897	Switch		1
10	X8903	Screw M4 x 6		2
11	X8946	Rivet		2
12	X8976	Warning Label		1
13	X9674-115.2-AL	Motor 115 VAC w/14uf Capacitor		1
Not Shown	X9674C	Capacitor 14uF		1
14	X1023	Fan Blade		1
15	X9676	Screw #8-18 x 3/4"		13
16	X9700	Bottom Housing		1
17	X9701	Top Housing		1
18	X9702	Bolt 1/4-20 x 2-3/4"		5
19	X9704	Screw #8-18 x 3/1/2"		2
20	X9705	Rubber Grommet		1
21	X9719	Power Cord 18/3 x 20' SJTW		1
22	X9726-TOR	Front Label		1
23	X9727	Warning Label		1
24	X9728-TOR	Switch Label		1

Ref Number	Part Number	Part Description	Context Notes	Quantity
25	X9731	Cap		4
26	X9831	Knob		1

Wiring Diagram



Rendered by LeadVenture, Inc.

Wiring Diagram

Ref Number	Part Number	Part Description	Context Notes	Quantity
------------	-------------	------------------	---------------	----------